



PowerWatch Country Guide

Afghanistan	220 V	50 Hz	PWV-002-E
Albania	220 V	50 Hz	PWV-002-E
Algeria	230 V	50 Hz	PWV-002-E
American Samoa	120 V	60 Hz	PWV-001
Andorra	230 V	50 Hz	PWV-002-E
Angola	220 V	50 Hz	PWV-002-E
Anguilla	110 V	60 Hz	PWV-001
Antigua	230 V	60 Hz	Consult Factory
Argentina	220 V	50 Hz	PWV-002-E
Armenia	220 V	50 Hz	PWV-002-E
Aruba	127 V	60 Hz	PWV-001
Australia	240 V	50 Hz	PWV-002-A
Austria	230 V	50 Hz	PWV-002-E
Azerbaijan	220 V	50 Hz	PWV-002-E
Azores	220 V	50 Hz	PWV-002-E
Bahamas	120 V	60 Hz	PWV-001
Bahrain	110/230 V	60/50 Hz	PWV-001, PWV-002-U
Balearic Islands	220 V	50 Hz	PWV-002-E
Bangladesh	220 V	50 Hz	PWV-002-E, PWV-002-U
Barbados	115V	50 Hz	PWV-001
Belarus	220 V	50 Hz	PWV-002-E
Belgium	230 V	50 Hz	PWV-002-E
Belize	110/220 V	60 Hz	PWV-001, PWV-002-U
Benin	220 V	50 Hz	PWV-002-E
Bermuda	120 V	60 Hz	PWV-001
Bhutan	230 V	50 Hz	PWV-002-E, PWV-002-U
Bolivia	115/230 V	50 Hz	PWV-001, PWV-002-E
Bosnia	220 V	50 Hz	PWV-002-E
Botswana	230V	50 Hz	Consult Factory
Brazil	110/220 V	60 Hz	PWV-001, PWV-002-E
Brunei	240 V	50 Hz	PWV-002-U
Bulgaria	230 V	50 Hz	PWV-002-E
Burkina Faso	220 V	50 Hz	PWV-002-E
Burundi	220 V	50 Hz	PWV-002-E
Cambodia	230 V	50 Hz	PWV-002-E
Cameroon	220 V	50 Hz	PWV-002-E
Canada	120/240 V	60 Hz	PWV-001, PWV-002-E, PWA-001



PowerWatch Country Guide Cont.

Canary Islands	220 V	50 Hz	PWV-002-E, PWA-002
Cape Verde	220 V	50 Hz	PWV-002-E
Cayman Islands	120 V	60 Hz	PWV-001
Central African Republic	220 V	50 Hz	PWV-002-E
Chad	220 V	50 Hz	PWV-002-E
Channel Islands	230 V	50 Hz	PWV-002-U
Chile	220 V	50 Hz	PWV-002-E, PWA-002
China	220 V	50 Hz	Consult Factory
Colombia	110 V	60 Hz	PWV-001
Comoros	220 V	50 Hz	PWV-002-E
Congo	230 V	50 Hz	PWV-002-E
Cook Islands	240 V	50 Hz	PWV-002-A
Costa Rica	120 V	60 Hz	PWV-001
Côte d'Ivoire	220 V	50 Hz	PWV-002-E
Croatia	230 V	50 Hz	PWV-002-E
Cuba	110/220 V	60 Hz	PWV-001, PWV-002-E, PWVA-002
Cyprus	240 V	50 Hz	PWV-002-U
Czech Republic	230 V	50 Hz	PWV-002-E
Denmark	230 V	50 Hz	PWV-002-E
Djibouti	220 V	50 Hz	PWV-002-E
Dominica	230 V	50 Hz	PWV-002-U
Dominican Republic	110 V	60 Hz	PWV-001
East Timor	220 V	50 Hz	PWV-002-A, PWV-002-E
Ecuador	120-127 V	60 Hz	PWV-001
Egypt	220 V	50 Hz	PWV-002-E
El Salvador	115V	60 Hz	PWV-001
Equatorial Guinea	220 V	50 Hz	PWV-002-E
Eritrea	230 V	50 Hz	PWV-002-E
Estonia	230 V	50 Hz	PWV-002-E
Ethiopia	220 V	50 Hz	PWV-002-E, PWA-002, PWA-003
Faeroe Islands	220 V	50 Hz	PWV-002-E
Falkland Islands	240 V	50 Hz	PWV-002-U
Fiji	240 V	50 Hz	PWV-002-A
Finland	230 V	50 Hz	PWV-002-E
France	230 V	50 Hz	PWV-002-E
French Guiana	220 V	50 Hz	PWV-002-E
Gaza	230 V	50 Hz	Consult Factory
Gabon	220 V	50 Hz	PWV-002-E
Gambia	230 V	50 Hz	PWV-002-U
Georgia	220 V	50 Hz	PWV-002-E
Germany	230 V	50 Hz	PWV-002-E



PowerWatch Country Guide Cont.

Germany	230 V	50 Hz	PWV-002-E
Ghana	230 V	50 Hz	PWV-002-U
Gibraltar	240 V	50 Hz	PWV-002-E, PWV-002-U
Greece	220 V	50 Hz	PWV-002-E
Greenland	220 V	50 Hz	PWV-002-E
Grenada	230 V	50 Hz	PWV-002-U
Guadeloupe	230 V	50 Hz	PWV-002-E
Guam	110 V	60 Hz	PWV-001
Guatemala	120 V	60 Hz	PWV-001
Guinea	220 V	50 Hz	PWV-002-E
Guinea-Bissau	220 V	50 Hz	PWV-002-E
Guyana	240 V	60 Hz	PWV-001, PWV-002-U
Haiti	110 V	60 Hz	PWV-001
Honduras	110 V	60 Hz	PWV-001
Hong Kong	220 V	50 Hz	PWV-002-U
Hungary	230 V	50 Hz	PWV-002-E
Iceland	220 V	50 Hz	PWV-002-E
India	230 V	50 Hz	PWV-002-E
Indonesia	230 V	50 Hz	PWV-002-E, PWV-002-U
Iran	230 V	50 Hz	PWV-002-E
Iraq	230 V	50 Hz	PWV-002-E, PWV-002-U
Ireland (Eire)	230 V	50 Hz	PWV-002-U
Isle of Man	240 V	50 Hz	PWV-002-E, PWV-002-U
Israel	220 V	50 Hz	PWV-002-E
Italy	230 V	50 Hz	PWV-002-E, PWA-002
Jamaica	110 V	50 Hz	PWV-001
Japan	100 V	50/60 Hz	PWV-001
Jordan	230 V	50 Hz	PWV-002-E, PWV-002-U, PWA-003
Kenya	240 V	50 Hz	PWV-002-U
Kazakhstan	220 V	50 Hz	PWV-002-E
Kiribati	240 V	50 Hz	PWV-002-A
Korea, South	220 V	60 Hz	PWV-002-E
Kuwait	240 V	50 Hz	PWV-002-U
Laos	230 V	50 Hz	PWV-002-E
Latvia	220 V	50 Hz	PWV-002-E
Lebanon	110/220 V	50 Hz	PWV-001, PWV-002-E, PWV-002-U
Lesotho	220 V	50 Hz	Consult Factory
Liberia	120 V	60 Hz	PWV-001
Libya	230 V	50 Hz	PWV-002-E, PWA-002
Lithuania	220 V	50 Hz	PWV-002-E
Liechtenstein	230 V	50 Hz	PWV-002-E, PWA-003



Toll-Free 1.800.663.7845
 Phone 1.604.591.1128
 sales@acrsystems.com

www.acrsystems.com
 ISO9001:2000 Certified
 © ACR Systems Inc.

Document No. 00-0667
 Release Date 23/7/08
 Page 3/6 Revision -

PowerWatch Country Guide Cont.

Luxembourg	220 V	50 Hz	PWV-002-E
Macau	220 V	50 Hz	PWV-002-E, PWV-002-U
Macedonia	220 V	50 Hz	PWV-002-E
Madagascar	220 V	50 Hz	PWV-002-E
Madeira	220 V	50 Hz	PWV-002-E
Malawi	230 V	50 Hz	PWV-002-U
Malaysia	240 V	50 Hz	PWV-002-U
Maldives	230 V	50 Hz	PWV-002-E, PWA-002, PWA-003, PWV-002-U
Mali	220 V	50 Hz	PWV-002-E
Malta	240 V	50 Hz	PWV-002-U
Martinique	220 V	50 Hz	PWV-002-E
Mauritania	220 V	50 Hz	PWV-002-E
Mauritius	230 V	50 Hz	PWV-002-E, PWV-002-U
Mexico	127 V	60 Hz	PWV-001
Micronesia	120 V	60 Hz	PWV-001
Monaco	127/220 V	50 Hz	PWV-002-E
Mongolia	220 V	50 Hz	PWV-002-E
Montenegro	220 V	50 Hz	PWV-002-E
Montserrat	230 V	60 Hz	Consult Factory
Morocco	220 V	50 Hz	PWV-002-E
Mozambique	220 V	50 Hz	PWV-002-E
Myanmar	230 V	50 Hz	PWV-002-E, PWV-002-U
Namibia	220 V	50 Hz	Consult Factory
Nauru	240 V	50 Hz	PWV-002-A
Nepal	230 V	50 Hz	PWV-002-E
Netherlands	230 V	50 Hz	PWV-002-E
Netherlands Antilles	127/220 V	50 Hz	PWV-001, PWV-002-E
New Caledonia	220 V	50 Hz	PWV-002-E
New Zealand	230 V	50 Hz	PWV-002-A
Nicaragua	120 V	60 Hz	PWV-001
Niger	220 V	50 Hz	PWV-002-E
Nigeria	240 V	50 Hz	PWV-002-E, PWV-002-U
Norway	230 V	50 Hz	PWV-002-E
Okinawa	100 V	60 Hz	PWV-001
Oman	240 V	50 Hz	PWV-002-U
Pakistan	220 V	50 Hz	PWV-002-E
Palmyra Atoll	120 V	60 Hz	PWV-001
Panama	110 V	60 Hz	PWV-001
Papua New Guinea	240 V	50 Hz	PWV-002-A
Paraguay	220 V	50 Hz	PWV-002-E



PowerWatch Country Guide Cont.

Peru	220 V	60 Hz	Consult Factory
Philippines	220 V	60 Hz	Consult Factory
Poland	230 V	50 Hz	PWV-002-E
Portugal	230 V	50 Hz	PWV-002-E
Puerto Rico	120 V	60 Hz	PWV-001
Qatar	240 V	50 Hz	PWV-002-E, PWV-002-U
Réunion Island	220 V	50 Hz	PWV-002-E
Romania	230 V	50 Hz	PWV-002-E
Russia	220 V	50 Hz	PWV-002-E
Rwanda	230 V	50 Hz	PWV-002-E, PWA-003
St. Kitts and Nevis	230 V	60 Hz	PWV-002-E, PWV-002-U
St. Lucia	240 V	50 Hz	PWV-002-U
St. Vincent	230 V	50 Hz	PWV-002-A, PWV-002-E, PWV-002-U
Samoa	230 V	50 Hz	PWV-002-A
Saudi Arabia	127/220 V	60 Hz	PWV-001, PWV-002-E, PWV-002-U
Senegal	230 V	50 Hz	PWV-002-E
Serbia	220 V	50 Hz	PWV-002-E
Seychelles	240 V	50 Hz	PWV-002-U
Sierra Leone	230 V	50 Hz	PWV-002-E, PWV-002-U
Singapore	230 V	50 Hz	PWV-002-U
Slovak Republic	230 V	50 Hz	PWV-002-E
Slovenia	220 V	50 Hz	PWV-002-E
Somalia	220 V	50 Hz	PWV-002-E
South Africa	220/230 V	50 Hz	Consult Factory
Spain	230 V	50 Hz	PWV-002-E
Sri Lanka	230 V	50 Hz	Consult Factory
Sudan	230 V	50 Hz	PWV-002-E
Suriname	127 V	60 Hz	Consult Factory
Swaziland	230 V	50 Hz	Consult Factory
Sweden	230 V	50 Hz	PWV-002-E
Switzerland	230 V	50 Hz	PWV-002-E, PWA-003
Syria	220 V	50 Hz	PWV-002-E, PWA-002
Tahiti	110/220 V	60 Hz	PWV-001, PWV-002-E
Tajikistan	220 V	50 Hz	PWV-002-A, PWV-002-E
Taiwan	110 V	60 Hz	PWV-001
Tanzania	230 V	50 Hz	PWV-002-E, PWV-002-U
Thailand	220 V	50 Hz	PWV-002-E
Togo	220 V	50 Hz	PWV-002-E
Tonga	240 V	50 Hz	PWV-002-A
Trinidad & Tobago	115V	60 Hz	PWV-001
Tunisia	230 V	50 Hz	PWV-002-E



PowerWatch Country Guide Cont.

Turkey	230 V	50 Hz	PWV-002-E
Turkmenistan	220 V	50 Hz	PWV-002-E
Uganda	240 V	50 Hz	PWV-002-U
Ukraine	220 V	50 Hz	PWV-002-E
United Arab Emirates	220 V	50 Hz	PWV-002-U
United Kingdom	230 V	50 Hz	PWV-002-U
United States	120/240 V	60 Hz	PWV-001, PWV-002-E, PWA-001
Uruguay	220 V	50 Hz	PWV-002-E, PWA-002
Uzbekistan	220 V	50 Hz	PWV-002-A, PWV-002-E
Vanuatu	230 V	50 Hz	PWV-002-A
Venezuela	120 V	60 Hz	PWV-001
Vietnam	220 V	50 Hz	PWV-002-E, PWV-002-U
Virgin Islands	115 V	60 Hz	PWV-001
Yemen	220/230 V	50 Hz	PWV-002-U
Zambia	230 V	50 Hz	PWV-002-U
Zimbabwe	220 V	50 Hz	PWV-002-U



Toll-Free 1.800.663.7845
Phone 1.604.591.1128
sales@acrsystems.com

www.acrsystems.com
ISO9001:2000 Certified
© ACR Systems Inc.

Document No. 00-0667
Release Date 23/7/08
Page 6/6 Revision -